



Description	Description
Brother DR350 Reman Drum PR	Brother DR350 Remanufactured Drum PR (12,000 Yield). For Use In: DCP-7020, HL-2040, HL-2070N, IntelliFax-2820, IntelliFax-2910, IntelliFax-2920, MFC-7220, MFC-7225N, MFC-7420, MFC-7820N. We recommend using Brother toners and drums from the same manufacturer.
Brother DR360 Reman Drum PR	Brother DR360 Remanufactured Drum PR (12,000 Yield). For Use In: HL-2140, HL-2170W, MFC-7340, MFC-7345N, MFC-7440N, MFC-7840W, DCP-7030, DCP-7040. We recommend using Brother toners and drums from the same manufacturer.
Brother DR420 Reman Drum PR	Brother DR420 Remanufactured Drum PR (12,000 Yield). For Use In: Brother HL-2220, HL-2230, HL-2240, HL-2240D, HL-2270DW, HL-2280DW, DCP-7060D, DCP-7065DN, MFC-7240, MFC-7360N, MFC-7460DN, MFC-7860DW, IntelliFax-2840, IntelliFax-2940. We recommend using Brother toners and drums from the same manufacturer.
Brother TN350 Reman Toner PR	Brother TN350 Remanufactured Toner PR (2,500 Yield). For Use In: DCP-7020, HL-2040, HL-2070N, IntelliFax-2820, IntelliFax-2910, IntelliFax-2920, MFC-7220, MFC-7225N, MFC-7420, MFC-7820N. We recommend using Brother toners and drums from the same manufacturer.
Brother TN360 Reman Toner PR	Brother TN360 Remanufactured High Yield Toner PR (2,600 Yield). Also Replaces TN330. For Use In: Brother HL-2140, HL-2170W, DCP-7030, DCP-7040, MFC-7340, MFC-7345N, MFC-7440N, MFC-7840W. We recommend using Brother Toner and Drums from the same Manufacturer.
Brother TN450 Reman Toner PR	Brother TN450 Remanufactured High Yield Toner PR (2,600 Yield). Also Replaces TN420. For Use In: Brother HL-2220, HL-2230, HL-2240, HL-2240D, HL-2270DW, HL-2280DW, DCP-7060D, DCP-7065DN, MFC-7240, MFC-7360N, MFC-7460DN, MFC-7860DW, IntelliFax-2840, IntelliFax-2940. We recommend using Brother toner and drums from the same manufacturer.
Brother TN560 Reman Toner PR	Brother TN560 Remanufactured High Yield Toner PR (6,500 Yield). Also Replaces TN530. For Use In: DCP-8020, DCP-8025D, HL-1650, HL-1650N, HL-1650NPLUS, HL-1670N, HL-1850, HL-1870n, HL-5040, HL-5050, HL-5050LT, HL-5070N, MFC-8420, MFC-8820D, MFC-8820DN. We recommend using Brother toner and drums from the same manufacturer.
Brother TN570 Reman Toner PR	Brother TN570 Remanufactured High Yield Toner PR (6,700 Yield). Also Replaces TN540. For Use In: DCP-8040, DCP-8045D, HL-5140, HL-5150D, HL-5150DLT, HL-5170DN, HL-5170DNL, MFC-8120, MFC-8220, MFC-8440, MFC-8640D, MFC-8840D, MFC-8840DN. We recommend using Brother toner and drums from the same manufacturer.
Brother TN580 Reman Toner PR	Brother TN580 Remanufactured High Yield Toner PR (7,000 Yield). Also Replaces TN550. For Use In: DCP-8060, DCP-8065DN, HL-5240, HL-5250DN, HL-5250DNT, HL-5280DW, MFC-8460N, MFC-8660DN, MFC-8670DN, MFC-8860DN, MFC-8870DW. We recommend using Brother toner and drums from the same manufacturer.
Brother TN650 Reman Toner PR	Brother TN650 Remanufactured High Yield Toner PR (8,000 Yield). Also replaces TN620. For Use In: HL-5340D, HL-5370DW, HL-5370DWT, MFC-8480DN, MFC-8680DN, MFC-8890DW, DCP-8080DN, DCP-8085DN. We recommend using Brother toner and drums from the same manufacturer.
Dell 2330 Reman HY Toner PR	Dell 2330 2350 Remanufactured Extended High Yield Toner PR (9,000 Yield). For Use In: Dell 2330D, 2330DN, 2350D, 2350DN. Replaces Dell PK941 High Yield 6,000 Yield.
Dell 2335 Reman HY Toner PR	Dell 2335DN Remanufactured High Yield Toner PR (NX994) (330-2209) (6,000 Yield). Also works in Dell 2355DN.
Dell B2360D (M11XH) Reman Toner 8.5K PR	Dell B2360D (M11XH) Remanufactured Toner PR (8,500 Yield). For Use In: Dell B2360D, B2360DN, B3460DN, B3465DN, B3465DNF. Dell Reorder #: 331-9805.
HP 126A CE310A Reman Blk Toner PR	HP 126A CE310A Remanufactured Black Toner PR (1,200 Yield). For Use In: HP Color LaserJet CP1020, CP1025NW, M175NW, M275.
HP 126A CE311A Reman Cyn Toner PR	HP 126A CE311A Remanufactured Cyan Toner PR (1,000 Yield). For Use In: HP Color LaserJet CP1020, CP1025NW, M175NW, M275.
HP 126A CE312A Reman Yel Toner PR	HP 126A CE312A Remanufactured Yellow Toner PR (1,000 Yield). For Use In: HP Color LaserJet CP1020, CP1025NW, M175NW, M275.
HP 126A CE313A Reman Mag Toner PR	HP 126A CE313A Remanufactured Magenta Toner PR (1,000 Yield). For Use In: HP Color LaserJet CP1020, CP1025NW, M175NW, M275.
HP 128A CE320A Reman Blk Toner PR	HP 128A CE320A Remanufactured Black Toner PR (2,000 Yield). For Use In: HP Color LaserJet CP1525nw, CM1415 MFP.
HP 128A CE321A Reman Cyn Toner PR	HP 128A CE321A Remanufactured Cyan Toner PR (1,300 Yield). For Use In: HP Color LaserJet CP1525nw, CM1415 MFP.
HP 128A CE322A Reman Yel Toner PR	HP 128A CE322A Remanufactured Yellow Toner PR (1,300 Yield). For Use In: HP Color LaserJet CP1525nw, CM1415 MFP.
HP 128A CE323A Reman Mag Toner PR	HP 128A CE323A Remanufactured Magenta Toner PR (1,300 Yield). For Use In: HP Color LaserJet CP1525nw, CM1415 MFP.



HP 304A CC530A Reman Blk Toner PR	HP 304A CC530A Remanufactured Black Toner PR (3,500 Yield). For Use In: HP Color LaserJet CP2025, CM2320 MFP. Canon 118 Black (2662B001AA) (CRG-118BK). Canon ImageClass MF8350CDN.
HP 304A CC531A Reman Cyn Toner PR	HP 304A CC531A Remanufactured Cyan Toner PR (2,800 Yield). For Use In: HP Color LaserJet CP2025, CM2320 MFP. Canon 118 Cyan (2661B001AA) (CRG-118C). Canon ImageClass MF8350CDN.
HP 304A CC532A Reman Yel Toner PR	HP 304A CC532A Remanufactured Yellow Toner PR (2,800 Yield). For Use In: HP Color LaserJet CP2025, CM2320 MFP. Also Replaces Canon 118 Yellow (2659B001AA) (CRG-118Y). Canon ImageClass MF8350CDN.
HP 304A CC533A Reman Mag Toner PR	HP 304A CC533A Remanufactured Magenta Toner PR (2,800 Yield). For Use In: HP Color LaserJet CP2025, CM2320 MFP. Also Replaces Canon 118 Magenta (2660B001AA) (CRG-118M). Canon ImageClass MF8350CDN.
HP 504A CE250A Reman Blk Toner PR	HP 504A CE250A Remanufactured Black Toner PR (5,000 Yield). For Use In: HP Color LaserJet CP3525, CM3530 MFP.
HP 504A CE251A Reman Cyn Toner PR	HP 504A CE251A Remanufactured Cyan Toner PR (7,000 Yield). For Use In: HP Color LaserJet CP3525, CM3530 MFP.
HP 504A CE252A Reman Yel Toner PR	HP 504A CE252A Remanufactured Yellow Toner PR (7,000 Yield). For Use In: HP Color LaserJet CP3525, CM3530 MFP.
HP 504A CE253A Reman Mag Toner PR	HP 504A CE253A Remanufactured Magenta Toner PR (7,000 Yield). For Use In: HP Color LaserJet CP3525, CM3530 MFP.
HP 504X CE250X Reman Blk Toner PR	HP 504X CE250X Remanufactured High Yield Black Toner PR (10,500 Yield). For Use In: HP Color LaserJet CP3525, CM3530 MFP. High Yield Replacement For HP 504A CE250A.
HP C4092A 1100 Reman Toner PR	HP C4092A Remanufactured Toner PR (2,500 Yield). For Use In: HP LaserJet 1100, 3200.
HP C4096A 2100 Reman Toner PR	HP C4096A Remanufactured Toner PR (5,000 Yield). For Use In: HP LaserJet 2100, 2200.
HP C8543X 9000 9040 Reman Toner PBX	HP C8543X Remanufactured Toner PBX (30,000 Yield). For Use In: HP LaserJet 9000, 9040, 9050, M9040mfp, M9050mfp.
HP CB435A P1005 Reman Toner PR	HP CB435A Remanufactured Toner PR (1,500 Yield). For Use In: HP LaserJet P1005, P1006.
HP CB436A P1505 Reman Toner PR	HP CB436A Remanufactured Toner PR (2,000 Yield). For Use In: HP LaserJet P1505, M1522.
HP CC364A P4014 Reman Toner PR	HP CC364A Remanufactured Toner PR (10,000 Yield). For Use In: HP LaserJet P4014, P4015, P4515.
HP CC364X P4015 Reman Toner PR	HP CC364X Remanufactured High Yield Toner PR (24,000 Yield). For Use In: HP LaserJet P4015 P4515. Not For Use In: LaserJet P4014.
HP CE255A P3015 Reman Toner PR	HP CE255A Remanufactured Toner PR (6,000 Yield). For Use In: HP LaserJet P3010, P3015, P3016, Enterprise M525 Series.
HP CE255X P3015 Reman Toner PR	HP CE255X Remanufactured Toner PR (12,500 Yield). For Use In: HP LaserJet P3010, P3015, P3016, Enterprise M525 Series.
HP CE278A P1606 Reman Toner PR	HP CE278A Remanufactured Toner PR (2,100 Yield). For Use In: HP LaserJet P1606DN, M1536DNF MFP.
HP CE285A P1102 Reman Toner PR	HP CE285A Remanufactured Toner PR (1,600 Yield). For Use In: HP LaserJet Pro P1102W, M1212NF MFP, M1217NFW MFP.
HP CE390A M4555 Reman Toner PR	HP CE390A Remanufactured Toner PR (10,000 Yield). For Use In: HP LaserJet Enterprise 600 models M601, M602, M603, & M4555MFP.
HP CE390X M4555 Reman Toner PR	HP CE390X Remanufactured Toner PR (24,000 Yield). For Use In: HP LaserJet Enterprise 600 models M602, M603, & M4555MFP. Not For Use In LaserJet Enterprise 600 model M601.
HP CE505A P2035 Reman Toner PR	HP CE505A Remanufactured Toner PR (2,300 Yield). For Use In: HP LaserJet P2035, P2055.
HP CE505X P2055 Reman Toner PR	HP CE505X Remanufactured Toner PR (6,500 Yield). For Use In: HP LaserJet P2055.
HP CF280A Reman Toner PR	HP CF280A Remanufactured Toner PR (2,700 Yield). For Use In: HP LaserJet Pro 400. (Caution: Not the Same as HP LaserJet Pro 400 Color.)
HP CF280X Reman Toner PR	HP CF280X Remanufactured Toner PR (6,900 Yield). For Use In: HP LaserJet Pro 400. (Caution: Not the Same as HP LaserJet Pro 400 Color.)
HP 38A 42X Jumbo Uni Reman Toner PR	HP Q1338A Q1339A Q5942X Q5945A Jumbo Universal Remanufactured Toner PR(30,0000 Yield). For Use In: HP LaserJet 4200, 4250, 4300, 4350, 4345mfp, M4345mfp. Not for Use in HP LaserJet 4240.
HP Q1338A 4200 Reman Toner PR	HP Q1338A Remanufactured Toner PR (12,000 Yield). For Use In: HP LaserJet 4200.
HP Q1339A 4300 Reman Toner PR	HP Q1339A Remanufactured Toner PR (18,000 Yield). For Use In: HP LaserJet 4300.
HP Q2610A 2300 Reman Toner PR	HP Q2610A Remanufactured Toner PR (6,000 Yield). For Use In: HP LaserJet 2300.
HP Q2612A 1012 Reman Toner PR	HP Q2612A Remanufactured Toner PR (2,000 Yield). For Use In: HP LaserJet 1012, 1018, 1020, 1022, 3015, 3020, 3030, 3050, 3052, 3055, M1319F MFP.
HP Q2612X 1012 Reman Toner PR	HP Q2612X Remanufactured High Yield Toner PR (3,000 Yield). For Use In: HP LaserJet 1012, 1018, 1020, 1022, 3015, 3020, 3030, 3050, 3052, 3055, M1319F MFP.



HP Q5942A 4250 Reman Toner PR	HP Q5942A Remanufactured Toner PR (10,000 Yield). For Use In: HP LaserJet 4240, 4250, 4350.
HP Q5942X 4250 Reman Toner PR	HP Q5942X Remanufactured High Yield Toner PR (20,000 Yield). For Use In: HP LaserJet 4250, 4350.
HP Q5949A 1160 Reman Toner PR	HP Q5949A Remanufactured Toner PR (2,500 Yield). For Use In: HP LaserJet 1160, 1320, 3390.
HP Q5949X 1320 Reman Toner PR	HP Q5949X Remanufactured Toner PR (6,000 Yield). For Use In: HP LaserJet 1320, 3390.
HP Q6511A 2420 Reman Toner PR	HP Q6511A Remanufactured Toner PR (6,000 Yield). For Use In: HP LaserJet 2420 2430.
HP Q6511X 2420 Reman Toner PR	HP Q6511X Remanufactured Toner PR (12,000 Yield). For Use In: HP LaserJet 2420, 2430.
HP Q7551A P3005 Reman Toner PR	HP Q7551A Remanufactured Toner PR (6,500 Yield). For Use In: HP LaserJet P3005, M3027mfp, 3035mfp.
HP Q7551X P3005 Reman Toner PR	HP Q7551X Remanufactured Toner PR (13,000 Yield). For Use In: HP LaserJet P3005, M3027MFP, M3035MFP.
HP Q7553A P2015 Reman Toner PR	HP Q7553A Remanufactured Toner PR (3,000 Yield). For Use In: HP LaserJet P2015, M2727NF MFP.
HP Q7553X P2015 Reman Toner PR	HP Q7553X Remanufactured High Yield Toner PR (7,000 Yield). For Use In: HP LaserJet P2015, M2727NF MFP.
Lexmark E330 Dell 1700 RemanTonerPR	Lexmark 34015HA Remanufactured High Yield Universal Toner PR (6,000 Yield). For Use In: Lexmark E232, E234, E240, E330, E332, E340, E342, X340, X342. Dell 1700, 1710. InfoPrint 14412, 1512. Toshiba 270P, 300P.
Lexmark E260 Reman Toner PR	Lexmark E260 Remanufactured Extended Yield Toner PR (5,000 Yield). Lexmark OEM is (3,500 Yield). For Use In: Lexmark E260, E360, E460, E462. Replaces Lexmark Supplies PartNumbers: E260A11A, E260A41G, E260A21A.
Lexmark MS310 (501H) Reman Toner 5K PR	Lexmark MS310 (501H) Remanufactured Toner PR (5,000 Yield). For Use In: Lexmark MS310, MS410, MS510, MS610. Replaces 50F1H00, 50FOHA0.
Lexmark MS410 (501X) Reman Toner 10K PR	Lexmark MS410 (501X) Remanufactured Toner PR (10,000 Yield). For Use In: Lexmark MS410, MS510, MS610. Replaces 50F1X00, 50FOXA0.
Lexmark MS510 (501U) Reman Toner 20K PR	Lexmark MS510 (501U) Remanufactured Toner PR (20,000 Yield). For Use In: Lexmark MS510, MS610. Replaces 50F1U00, 50FOUA0.
Lexmark MS710 MS810 (521H) Reman Toner 25K PR	Lexmark MS710 (521H) Remanufactured Toner PR (25,000 Yield). For Use In: MS710, MS711, MS810, MS811, MS812. Replaces 52D1H00, 52DOHA0.
Lexmark MS811 (521X) Reman Toner 45K PR	Lexmark MS811 (521X) Remanufactured Toner PR (45,000 Yield). For Use In: Lexmark MS711, MS811, MS812. Replaces 52D1X00.
Lexmark MX310 (601H) Reman Toner 10K PR	Lexmark MX310 (601H) Remanufactured Toner PR (10,000 Yield). For Use In: Lexmark MX310, MX410, MX510, MX511, MX610, MX611. Replaces 60F1H00, 60FOHA0.
Lexmark MX510 (601X) Reman Toner 20K PR	Lexmark MX510 (601X) Remanufactured Toner PR (20,000 Yield). For Use In: Lexmark MX510, MX511, MX610, MX611. Replaces 60F1X00.
Lexmark MX710 (621H) Reman Toner 25K PR	Lexmark MX710 (621H) Remanufactured Toner PR (25,000 Yield). For Use In: Lexmark MX710, MX711, MX810, MX811, MX812. Replaces 62D1H00.
Lexmark MX711 (621X) Reman Toner 45K PR	Lexmark MX711 (621X) Remanufactured Toner PR (45,000 Yield). For Use In: MX711, MX810, MX811, MX812. Replaces 62D1X00.
Lexmark T630 Reman XHY Toner PR	Lexmark T630 Remanufactured Extra High Yield Universal Toner PR (32,000 Yield). For Use In: Lexmark T630, T632, T632, X630, X632, X634. Dell M5200N, W5300N. InfoPrint 1332 1352 1372.
Lexmark T630 IBM 1332 Reman TonerPR	Lexmark T630 Remanufactured High Yield Universal Toner PR (21,000 Yield). For Use In: Lexmark T630, T632, T634, X630, X632, X634; Dell M5200N, W5300N; InfoPrint 1332, 1352, 1372.
Lexmark T640 Reman HY Toner PR	Lexmark T640 Remanufactured High Yield Universal Toner PR (21,000 Yield). For Use In: Lexmark T640, T642, T644, X642, X644, X646; Dell 5210, 5310; InfoPrint 1532, 1552, 1572, 1570MFP, 1572MFP, 1650MFP.
Lexmark T644 Reman XHY Toner PR	Lexmark T640 T642 T644 X642 X644 X646 Dell 5210N 5310N Infoprint 1532 1552 1572 Remanufactured Extra High Yield Universal Toner PR (32,000 Yield).
Lexmark T650 Reman HY Toner PR	Lexmark T650 Remanufactured High Yield Toner PR (25,000 Yield). For Use In: Lexmark T650, T652, T654, T656. Replaces Lexmark supply number's: T650H11A, T650H21A, T650H41G. (This is a dedicated chip this toner will only function in these printer models.)
Lexmark T656 Reman XHY Toner PR	Lexmark T654 T656 Remanufactured Extra High Yield Toner PR (36,000 Yield). Replaces Lexmark Supplies: T654X11A, T654X41G. (Not For Use In: T650, T652, X651, X652, X654, X656, X658.)